


THEORY OF METAL CUTTING

What is required for machining?

Depth of Cut - Preset interference between tool and work piece

Feed - Motion to bring in additional material for machining

Speed - What generates the basic wedge and cuts



Machine Classifications




- 2 Turning Center or Lathe
- 2 Vertical Machining Centre (VMC)
- 2 Horizontal Machining Centre (HMC)
- 2 Special Purpose Machines (SPM)

Zones of Heat Generation

Shear Zone


Chip Tool Interface



Tool Work Interface

Heat Dissipation

80% Energy is converted to heat



18% of Energy is converted to heat

2% of energy converted to heat

TOOL WEAR



- 2 Gradual Tool Wear
 - 3 Unavoidable but controllable

- 2 Premature Wear or failure
 - 3 Avoidable

How Do We Rate Machinability?

- ⌘ Tool life in minutes
- ⌘ Cutting forces and Power consumed
- ⌘ Quality of Surface Finish
- ⌘ Chip formation
- ⌘ Material removal rate



Manufacturing

Technology

Broad classification of Engineering Manufacturing Processes.

- It is extremely difficult to tell the exact number of various manufacturing processes existing and are being practiced presently because very number of processes have been developed till now and the number is increasing exponentially with the growing demands and rapid progress science and technology.
- However, all such manufacturing processes can be broadly classified four major groups as follows

Shaping or forming

- Manufacturing a solid product of definite size and shape from given material taken in three possible states:
 - in liquid or semi-liquid state - e.g., casting, injection moulding etc.
 - in solid state - e.g., forging rolling, extrusion, drawing etc.
 - in powder form - e.g., powder metallurgical process.

Manufacturing

Joining process Technology

- u Welding, brazing, soldering etc.

Removal or Cutting process

- u Machining (Traditional or Non-traditional), Grinding etc.

Regenerative manufacturing Process

- u Production of solid products in layer by layer from raw materials different form:
 - ∞ liquid - e.g., stereo lithography
 - ∞ powder - e.g., selective sintering
 - ∞ sheet - e.g., LOM (laminated object manufacturing)
 - ∞ wire - e.g., FDM. (Fused Deposition Modeling)

Out of the fore said groups, **Regenerative Manufacturing is the latest** which is generally accomplished very rapidly and quite accurately using CAD and CAM for Rapid Prototyping and Tooling.

Manufacturing

Technology

Material Removal Processes – Metal Cutting Process

- 21 A family of shaping operations, the common feature of which is the removal of material from a starting work part so the remaining part has the desired geometry
- 21 **Traditional Process (Machining)** – Material removal by a sharp cutting tool, e.g., **turning, milling, drilling**
- 21 **Nontraditional processes** – Various energy forms other than sharp cutting tool to remove material. e.g., **Laser and Electron Beam machining**
- 21 **Abrasive processes** – Material removal by hard, abrasive particles, e.g., **grinding**

Manufacturing

Technology

Why Machining is Important

- 12 Variety of work materials can be machined
 - ∞ Most frequently used to cut metals
 - 12 Variety of part shapes and special geometric features possible, s
 - ∞ Screw threads
 - ∞ Accurate round holes
 - ∞ Very straight edges and surfaces
 - 12 Good dimensional accuracy and surface finish
-

Manufacturing

Technology

Disadvantages with Machining

❶ Wasteful of material

- ❧ Chips generated in machining are wasted material, at least unit operation

❷ Time consuming

- ❧ A machining operation generally takes more time to shape a part than alternative shaping processes, such as casting, powder metallurgy, or forming
-

Manufacturing

Technology

Machining in Manufacturing Sequence

- ⌘ Generally performed after other manufacturing processes, such as casting, forging, and bar drawing
 - ⌘ Other processes create the **general shape** of the starting work part
 - ⌘ **Machining** provides the **final shape, dimensions, finish, and special geometric details** that other processes cannot create
-

Manufacturing

Technology

Machining Operations

↳ Most important machining operations

- ↳ Turning

- ↳ Drilling

- ↳ Milling

↳ Other machining operations


- ↳ Shaping and planing

- ↳ Broaching

- ↳ Sawing

Manufacturing Technology


Turning



Single point cutting tool removes material from a rotating work piece to form a cylindrical shape

Manufacturing Technology


Drilling




Used to create a round hole, usually by means of a rotating tool (drill bit) with two cutting edges

Manufacturing Technology

Milling



(c) peripheral milling




(d) face milling.

Rotating multiple-cutting-edge tool is moved across work to cut a plane or straight surface

Manufacturing Technology

Machining requirements



The blank and the cutting tool are properly mounted (in fixtures) and moved in a precise device called machine tool enabling gradual removal of layer of material from the surface resulting in its desired dimensions and surface finish. Additionally, an environment called cutting fluid is generally used to ease machining by cooling and lubrication.

Manufacturing

Technology

Machine Tool - Definition

- ⌚ A **machine tool** is a non-portable power operated and reasonably valued device or system of devices in which energy is expended to produce jobs of desired size, shape and surface finish by removing excess material from the preformed blanks in the form of chips with the help of cutting tools moved past the work surface's.

Basic functions of Machine Tools

- ⌚ Machine Tools basically produce geometrical surfaces like cylindrical or any contour on the preformed blanks by machining work with the help of cutting tools.
-

Manufacturing

Technology

The physical functions of a Machine Tool in machining are

- 1. Firmly holding the blank and the tool
- 2. Transmit motions to the tool and the blank
- 3. Provide power to the tool-work pair for the machining action.
- 4. Control of the machining parameters, (speed, feed and depth of

Manufacturing

Technology

Classification of cutting tools

- **Single-Point Cutting Edge Tools**


- One dominant cutting edge
- Point is usually rounded to form a nose radius
- Turning uses single point tools

- **Multiple Point Cutting Edge Tools**


- More than one cutting edge
 - Motion relative to work achieved by rotating
 - Drilling and milling use rotating multiple cutting edge tools
-

Manufacturing Technology

Cutting Tools



a. Single-Point Cutting Tool




b. Multi-Point Cutting Tool

Figure (a) A single-point tool showing rake face, flank, and tool point; and (b) a milling cutter, representative of tools with multiple cutting edges.

Manufacturing

Technology

Tool signature for single point cutting tool



Manufacturing

Technology

Tool signature for single point cutting tool

- Shank
 - It is the main body of the tool
- Flank
 - The surface of the tool adjacent to the cutting edge
- Face
 - The surface on which the chip slides
- Nose
 - It is the point where the side cutting edge and end cutting edge intersect
- Nose Radius
 - Strengthens finishing point of tool
- Cutting Edge
 - It is the edge on the face of the tool which removes the material from work piece
- Side cutting edge angle
 - Angle between side cutting edge and the side of the tool shank

Manufacturing

Technology


Tool signature for single point cutting tool

- End cutting edge angle
 - Angle between end cutting edge and the line normal to the tool shank
- Side Relief angle
 - Angle between the portion of the side flank immediately below the cutting edge and a line perpendicular to the base of the tool, measured right angle to the side flank
- End Relief angle
 - Angle between the portion of the end flank immediately below the cutting edge and a line perpendicular to the base of the tool, measured right angle to the end flank
- Side Rake angle
 - Angle between the tool face and a line parallel to the base of the tool measured in a plane perpendicular to the base and the side cutting edge
- Back Rake angle
 - Angle between the tool face and a line parallel to the base of the tool measured in a plane perpendicular to the side cutting edge

Manufacturing

Technology


Single Point Cutting Tool Terminology-2D



Manufacturing

Technology

Single Point Cutting Tool Terminology - 3D



Manufacturing

Technology

Cutting Tool Materials

- ⌘ Carbon steels, High-speed steels
- ⌘ Cast carbides, Cemented carbides, Coated carbides
- ⌘ Cermets, Ceramic Tools
- ⌘ Polycrystalline Cubic Boron Nitride (PCBN)
- ⌘ Polycrystalline Diamond (PCD)

Properties of Cutting Tool Materials

- ⌘ Harder than work piece.
- ⌘ High toughness
- ⌘ High thermal shock resistance
- ⌘ Low adhesion to work piece material
- ⌘ Low diffusivity to work piece material

Manufacturing

Technology

Theory of Metal Cutting

- **Metal cutting or machining** is the process of producing a work part by removing unwanted material from a block of metal, in the form of chips.
- This process is most important since almost all the products get their final shape and size by metal removal, either directly or indirectly.




Figure (a) A cross-sectional view of the machining process, (b) tool with negative rake angle; compare with positive rake angle in (a).

Manufacturing

Technology



Orthogonal and oblique cutting

Orthogonal cutting

- ∞ The cutting edge of the tool is straight and perpendicular to the direction of motion. (surface finish)

Oblique cutting

- ∞ The cutting edge of the tool is set at an angle to the direction of motion. (depth of cut)



The Mechanism of Cutting


Cutting action involves shear deformation of work material to form a chip.

As chip is removed, new surface is exposed

Orthogonal Cutting - assumes that the cutting edge of the tool is set in a

position that is perpendicular to the direction of relative work tool

motion. This allows us to deal with forces that act only in one plane



(a) A cross-sectional view of the machining process, (b) tool with negative rake angle compare with positive rake angle in (a).


Mechanics of Orthogonal Cutting

Orthogonal Cutting

- Ideal Orthogonal Cutting is when the cutting edge of the tool is straight and perpendicular to the direction of motion.
- During machining, the material is removed in form of chips, are generated by shear deformation along a plane called the **shear plane**.
- The surface the chip flows across is called the face or **rake face**.
- The surface that forms the other boundary of the wedge is called the **flank**.
- The **rake angle** is the angle between the tool face and a line perpendicular to the cutting point of the work piece surface.

Mechanics of Orthogonal Cutting

The relief or clearance angle is the angle between the tool flank and the newly formed surface of the work piece angle.



Mechanics of Orthogonal Cutting


Orthogonal cutting model:

t_1 = undeformed chip thickness

t_2 = deformed chip thickness (usually $t_2 > t_1$)

α = rake angle

If we are using a lathe, t_1 is the feed per revolution.




The Mechanism of Cutting


Cutting

In turning, w = depth of cut and t = feed

1



The Mechanism of Cutting



Cutting force (F_c) is tangential and Thrust force is axial (F_t)

Cutting forces in a turning operation

Mechanics of Orthogonal Cutting

Chip thickness ratio (or) cutting ratio

$$\text{Cutting ratio} = \frac{t_1}{t_2}$$

where

- r = chip thickness ratio or cutting ratio
- t_1 = thickness of the chip prior to chip formation
- t_2 = chip thickness after separation

Which one is more correct?

$$r \geq 1$$
$$r \leq 1$$

Chip thickness after cut always greater than before, so chip ratio always less than 1.0

Mechanics of Orthogonal Cutting

Shear Plane Angle

- Based on the geometric parameters of the orthogonal model, shear

plane angle θ can be determined as:

$$\tan \omega = \frac{r \cos \epsilon}{1 - r \sin \epsilon}$$

where

- r = chip thickness ratio or cutting ratio;
- ϵ = Rake angle
- θ = Shear angle

Mechanics of Orthogonal Cutting

Shear Plane Angle Proof

$$t_1 = h \sin \theta, \quad t_2 = h \cos(\theta - \alpha)$$


$$r = \frac{t_1}{t_2} = \frac{h \sin \theta}{h \cos(\theta - \alpha)} = \frac{\sin \theta}{\cos \theta \cos \alpha + \sin \theta \sin \alpha}$$

$$r \cos \theta \cos \alpha + r \sin \theta \sin \alpha = \sin \theta$$

$$\frac{r \cos \theta \cos \alpha}{\sin \theta} + \frac{r \sin \theta \sin \alpha}{\sin \theta} = 1$$


$$\frac{r \cos \alpha}{\tan \theta} + r \sin \alpha = 1$$

$$\tan \theta = \frac{r \cos \alpha}{1 - r \sin \alpha}$$




Mechanics of Orthogonal Cutting


Shear Strain in chip formation



(a)



(b)



(c)

(a) chip formation depicted as a series of parallel plates sliding relative to each other, (b) the plates isolated to show shear strain, and (c) shear strain triangle used to derive strain

Mechanics of Orthogonal Cutting

Shear Strain in chip formation

Shear strain in machining can be computed from the following equation, based on the preceding parallel plate model:

$$\gamma = \tan(\theta - \phi) + \cot \theta$$

where

γ = shear strain

θ = shear angle

ϕ = rake angle of cutting tool

Mechanics of Orthogonal Cutting

Shear Strain Proof

From the shear strain triangle (image c -slide 35)

- $\gamma = AC/DB = (AD+DC)/DB$

- $\gamma = AD/DB + DC/DB$

- $AD/DB = \cot \theta$

- $DC/DB = \tan(\theta - \phi)$


- Therefore $\gamma = \cot \theta + \tan(\theta - \phi)$

$$\gamma = \tan(\theta - \phi) + \cot \theta$$

Manufacturing Technology

Chip formation

- Mechanics of metal cutting is greatly depend on the shape and s the chips formed.



More realistic view of chip formation, showing shear zone rather than she plane.

Also shown is the secondary shear zone resulting from tool-chip friction.

Manufacturing

Technology

Four Basic Type of Chips in Machining are

- Discontinuous chip
 - Continuous chip
 - Continuous chip with Built-up Edge (BUE)
 - Serrated chip
-



Manufacturing Technology

Discontinuous chip

- When brittle materials like cast iron are cut, the deformed material gets fractured very easily and thus the Chip produced is in the form of discontinuous segments

Reasons

- Brittle work materials
- Low cutting speeds
- Large feed and depth of cut
- High tool-chip friction





Manufacturing Technology

Continuous chip

- Continuous chips are normally produced when machining steel and ductile materials at high cutting speeds. The continuous chip width is like a ribbon flows along the rake face.

Reasons

- Ductile work materials
- High cutting speeds
- Small feeds and depths
- Sharp cutting edge
- Low tool-chip friction



(b)


Manufacturing Technology

Continuous chip with Built-up Edge (BUE)

- When the friction between tool and chip is high while machining ductile materials, some particles of chip adhere to the tool rake face near the tool tip. When such sizeable material piles upon the rake face, it acts as a cutting edge in place of the actual cutting edge is termed as built up edge (BUE). By the effect of work hardening, BUE is harder than the parent work material

Reasons

- 21 Ductile materials
- 21 Low-to-medium cutting speeds
- 21 Tool-chip friction causes portions of chip to adhere to rake face
- 21 BUE forms, then breaks off, cyclically




Manufacturing Technology

Serrated chip

- Semi Continuous (saw tooth appearance) chips produced when machining tool steels or Harden materials at high cutting speeds.

Reasons

- Ductile materials
- Low-to-medium cutting speeds
- Tool-chip friction causes portions of chip to adhere to rake face
- BUE forms, then breaks off, cyclically



(d)

Manufacturing Technology

Chip Breakers

- Long continuous chip are undesirable
- Chip breaker is a piece of metal clamped to the rake surface of the tool bends the chip and breaks it
- Chips can also be broken by changing the tool geometry, thereby controlling the chip flow

Fig. (a) Schematic illustration of the action of a chip breaker .(b) Chip breaker Clamp on the rake of a cutting tool. (c) Grooves in cutting tools acting as chip breakers

Force & Velocity Relationships


and the Merchant Equation

Manufacturing

Technology

Forces Acting on Chip

- Friction force F and Normal force to friction N
- Shear force F_s and Normal force to shear F_n



(a)


Forces in metal cutting: (a) forces acting on the chip in orthogonal cutting

Manufacturing

Technology

Cutting Force and Thrust Force

- ∞ F , N , F_s and F_n cannot be measured directly, in order to measure forces the forces acting on the tool to be measured initially
- ∞ Cutting force F_c and Thrust force F_t



Forces in metal cutting: (b) forces acting on the tool that can be measured

Manufacturing Technology

Resultant Forces

- ⌚ Vector addition of F and $N =$ resultant R
- ⌚ Vector addition of F_s and $F_n =$ resultant R'
- ⌚ Forces acting on the chip must be in balance:
 - ⌚ R' must be equal in magnitude to R
 - ⌚ R' must be opposite in direction to R
 - ⌚ R' must be collinear with R

Manufacturing Technology

Shear Stress


- Shear stress acting along the shear plane

$$S = \frac{F_s}{A_s}$$

- where A_s = area of the shear plane

$$A_s = \frac{t_1 w}{\sin \phi}$$

- Shear stress = shear strength of work material during cutting



Shear Stress- Effect of Higher Shear Plane


Angle

Shear angle and its


significance

Effect of Higher Shear Plane Angle

- Higher shear plane angle means smaller shear plane which means low shear force, cutting forces, power, and temperature



(a)




(b)

Effect of shear plane angle ϕ : (a) higher θ with a resulting lower shear plane area; (b) small corresponding larger shear plane area. Note that the rake angle is larger in (a), which tends shear angle according to the Merchant equation

Force Calculations

The forces and angles involved in cutting are drawn here,

Having seen the vector based determination of the cutting forces, we can now look at equivalent calculations:



$$\frac{F_s}{F_c} = \tan \alpha$$

Where μ = The coefficient of friction

F_s = shear force
 F_n = force normal to shear plane
 α = tool rake angle (positive as shown)
 θ = shear angle
 β = friction angle

Force Calculations


And, by trigonometry:

$$F = F_t \cos \alpha + F_c \sin \alpha,$$

$$F_s = F_c \cos \theta - F_t \sin \theta$$

$$N = F_c \cos \alpha - F_t \sin \alpha,$$

$$F_n = F_c \sin \theta + F_t \cos \theta$$



Where the Resultant force R is Given by

$$R = \sqrt{F_c^2 + F_t^2} = \sqrt{F_s^2 + F_n^2} = \sqrt{F^2 + N^2}$$

F_s = shear force
 F_n = force normal to shear plane
 α = tool rake angle (positive as shown)
 θ = shear angle
 β = friction angle

Force

We can write the cutting
and

thrust forces in terms of
the

shear force:

$$R = (F_c^2 + F_t^2)^{1/2} = (F_s^2 + F_n^2)^{1/2} = (F^2 + N^2)^{1/2}$$

$$F_c = R \cos(\beta - \alpha)$$


$$F_t = R \sin(\beta - \alpha)$$

$$F_s = R \cos(\theta + \beta - \alpha)$$

$$F_n = R \sin(\theta + \beta - \alpha)$$

$$F_c = \frac{F_s \cos(\beta - \alpha)}{\cos(\theta + \beta - \alpha)}$$

$$F_t = \frac{F_s \sin(\beta - \alpha)}{\cos(\theta + \beta - \alpha)}$$



F_s = shear force
 F_n = force normal to shear plane
 α = tool rake angle (positive as shown)
 θ = shear angle
 β = friction angle

Velocity Calculations

Having seen the vector based

determination of the cutting

forces, we can now look at $V_c =$ Cutting velocity (ft/min)

as set or measured on the machine

$V_s =$ Shearing


velocity
 $V_f =$ Frictional
 velocity

Using the sign rules:

$$\frac{V_s}{\sin 90^\circ} = \frac{V_c}{\sin 90^\circ}$$

$$V_s = \frac{V_c \sin 90^\circ}{\sin 90^\circ}$$

COS



Also,


$$V_f = \frac{V_c \cos \theta}{\sin 90^\circ}$$

COS

Cutting Force Vs Rake Angle

α

The effects of rake angle on cutting force are shown in the graph below,



Manufacturing

Technology

The Merchant Equation

- To determine θ he assumed the minimum energy principle applied to metal cutting so that the deformation process adjusted itself to a minimum energy condition.
- Of all the possible angles at which shear deformation can occur, the work material will select a shear plane angle θ that minimizes energy given by

$$\theta = 45^\circ - \frac{\phi}{2}$$

- Derived by Eugene Merchant

Manufacturing

Technology

What the Merchant Equation Tells Us

• To increase shear plane angle

• Increase the rake angle

(ϕ)

• Reduce the friction angle (β) or coefficient of friction

$$\phi = 45^\circ - \frac{\beta}{2}$$

Merchant's Force Circle

Merchant's Force Circle is a method for

calculating the various forces involved

1. In the cutting process, the cutting force is drawn vertically, and the tangential force (F_c) is drawn horizontally.

(These forces will all be in the lower left hand quadrant).


The origin in the centre of the page.

The scale should be enough to include both

is drawn horizontally, and the measured force (F_c) is drawn vertically.

(These forces will all be in the lower left

hand quadrant).



Merchant's Force Circle

Merchant's Force Circle

2. Draw in the resultant (R) of F_c and F_t .
3. Locate the centre of R, and draw a circle

that encloses vector R. If done correctly,

the heads and tails of all 3 vectors will

4. Draw in the cutting tool in the upper

right hand quadrant, taking care to draw


the correct rake angle (α) from the

5. Extend the line that is the cutting face of

the tool (at the same rake angle) through

the circle. This now gives the friction

vector (F).



Merchant's Force Circle

Merchant's Force Circle

6. A line can now be drawn from the head of the friction vector, to the head of the resultant vector

(R). This gives the normal vector (N). Also add a

friction angle (β) between vectors R and N.

As a side note recall that any vector can be broken into its components. Therefore,

mathematically, $R = F_c + F_t = F_s + F_n$

7. Next use the chip thickness, compared to the cut depth to find the shear force. To do this, the chip is drawn on before and after cut. Before


drawing, select some magnification factor and draw a chip thickness line (e.g. 200 times) to multiply both values by. Draw a

horizontal axis. Next draw a chip thickness line parallel to the horizontal axis. Draw a

vertical line (e.g. 200 times) to multiply both values by. Draw a

horizontal axis. Next draw a chip thickness line parallel to the horizontal axis. Draw a

vertical line (e.g. 200 times) to multiply both values by. Draw a



Merchant's Force Circle

Merchant's Force Circle

8. Draw a vector from the origin (tool point) towards


the intersection of the two chip lines, stopping at

the circle. The result will be a shear force vector

9. (F_s) . Also measure the shear force angle between F_s and F to the head of F and F to the head of F .
 Finally add the shear force normal (F_n) from the head of F to the head of F .

10. Use a scale and protractor to measure off all

distances (forces) and angles.



Merchant's Force Circle

Manufacturing

Technology

Power and Energy Relationships

There are a number of reasons for wanting to calculate the power consumed

in cutting. These numbers can tell us how fast we can cut, or how large the

motor on a machine must be. Having both the forces and velocities

found. The power to perform machining can be computed from the Merchant for Circle, we are able to calculate the power,

$$P_c = F_c \cdot V_c \text{ in kW}$$

$$P_c = F_c \cdot V_c / 33,000 \text{ in HP}$$

where

P = cutting power in
KW

F_c = cutting force in
KN

V_c = cutting speed in
m/min

Manufacturing

Technology

Power and Energy Relationships

There are a number of reasons for wanting to calculate the power consumed

in cutting. These numbers can tell us how fast we can cut, or how large the

motor on a machine must be. Having both the forces and velocities

found. The power to perform machining can be computed from with the Merchant for Circle, we are able to calculate the power,

$$P_c = F_c \cdot V_c \text{ in kW}$$

$$P_c = F_c \cdot V_c / 33,000 \text{ in HP}$$

where

P = cutting power in
KW

F_c = cutting force in
KN

V_c = cutting speed in
m/min

Manufacturing Technology

Power and Energy Relationships
 Gross power to operate the machine tool P_g or HP is given by

$$P_g = \frac{P_c}{E} \quad \text{or} \quad HP_g = \frac{HP_c}{E}$$

where

- E = mechanical efficiency of machine tool

- Typical E for machine tools is 90%

There are losses in the machine that must be considered when estimating the size of the electric motor required:

$$P_g = \frac{P_c}{E} + P_t$$

Where

- P_t = power required to run the machine at no-load conditions (hp or kW)

Manufacturing

Technology

Power and Energy Relationships

Useful to convert power into power per unit volume rate of metal cut to cut (one cubic inch per minute)

Called unit power, P_u or unit horsepower, HP

$$P_u = \frac{P_c}{MR}$$

or

$$HP_u = \frac{HP_c}{MR}$$

where R_{MR} = material removal rate

Manufacturing

Technology

Power and Energy Relationships

- Unit power is also known as the **specific energy U**

$$U = \frac{P_c}{R_{MRW}} = \frac{F_c V_c}{V_c t} = \frac{F_c}{W_1} t$$

Units for specific energy are typically N-m/mm³ or J/mm³ (in-lb/in³)

Specific energy is in fact pressure and sometimes is called **specific cutting pressure**:

$$U = \frac{F_c}{A}$$

Manufacturing

Technology

Cutting Temperature

- Approximately 98% of the energy in machining is converted into heat
- This can cause temperatures to be very high at the tool-chip interface
- The remaining energy (about 2%) is retained as elastic energy in the chip

High cutting temperatures


- Reduce tool life
 - Produce hot chips that pose safety hazards to the machine operator
 - Can cause inaccuracies in part dimensions due to thermal expansion of work material
-

Manufacturing

Technology

Process Parameters

- Speed (v), Feed (f), Depth of Cut (d)
- Material Removal Rate (MRR) = $f \times d \times v$



Manufacturing

Technology

Shear angle and its significance

- Shear angle(θ) is the angle made by the shear plane with cutting speed vector.
 - Shear angle is very important parameter in metal cutting.
Higher the shear angle, **better** is the cutting performance.
 - In metal cutting it is observed that a higher rake angles rise to higher shear angles
-

Manufacturing Technology

Tool Wear

- Tools get worn out due to long term usage



Types of Tool Wear

- Flank wear (VB)
 - It occurs on the relief face of the tool and the side relief angle.
- Crater wear (KT)
 - It occurs on the rake face of the tool.
- Notch wear or Chipping (VN)
 - Breaking away of a small piece from the cutting edge of the tool



Manufacturing Technology

Tool Wear



Flank wear rate based on cutting spe

Manufacturing Technology

Tool Wear





Fig (a) Flank and crater wear in a cutting tool. tool moves to the left. (b) View of the rake of a turning tool showing nose radius R and crater wear pattern on the rake face of the tool (c) View of the flank face of a turning tool, showing the average flank wear land VB and the depth-of-cut line (wear notch)

Manufacturing Technology

Tool Life

- Tool life represents the useful life of the tool, expressed generally in units from the start of cut to some end point defined by a failure criterion

Tool Life Prediction

- Taylor's tool life equation predicts tool failure based on flank wear of the

$$Vt_n = C$$

where V is the cutting speed, t is the tool life,

n is Taylor exponent.

$n=0.125$ for HSS

$n=0.25$ for Carbide

$n=0.5$ for Coated Carbide/Ceramic

C is a constant given for work piece material

Manufacturing Technology

Machinability

- ⌚ Machinability is a system property that indicates how easy a material is machined at low cost.
- ⌚ Good machinability may mean one or more of the following: cutting with minimum energy, minimum tool wear, good surface finish, etc.

Quantitative measures of machinability

- ⌚ **Machinability index:** an average rating stated in comparison with reference materials. This measure can be misleading.
 - ⌚ **Tool life:** service time in minutes or seconds to total failure by chipping or cracking of the tool at certain cutting speed, or the volume of material removed before total failure.
 - ⌚ **Surface finish** produced at standardized cutting speeds and feeds.
 - ⌚ **Others** based on cutting force, power, temperature, or chip formation.
-

Manufacturing

Technology

Machinable Materials

Good machinable materials should have the following properties

- ❧ Low ductility, low strain-hardening exponent (n), low fracture toughness
- ❧ Low shear strength (low TS), low hardness.
- ❧ A strong metallurgical bond (adhesion) between tool and work piece undesirable when it weakens the tool material.
- ❧ Very hard compounds, such as some oxides, all carbides, many intermetallic compounds, and elements such as silicon, embedded in the work piece material accelerate tool wear, thus should be avoided.
- ❧ Inclusions that soften at high temperatures are beneficial.
- ❧ High thermal conductivity is helpful.

Manufacturing Technology

Machinable Materials

12 Ferrous materials

- ∞ Carbon steels: annealed, heat-treated (spheroidized), cold worked
- ∞ Free-machining steels: special inclusions
- ∞ Alloy steels: hard
- ∞ Stainless steels: high strength, low thermal conductivity, high s hardening rate
- ∞ Cast iron: white, gray, nodular cast iron

12 Non-ferrous materials

- ∞ Zinc, Magnesium, Aluminum alloys, Beryllium, Copper-based allo
Nickel-based alloys and super alloys,
- ∞ Titanium, Plastics, composites.

Manufacturing

Technology

Factors Affecting Machining

TABLE

Parameter	Influence and interrelationship
Cutting speed, depth of cut, feed, cutting fluids	Forces, power, temperature rise, tool life, type of chip, surface finish
Tool angles	As above, influence on chip flow direction, resistance to tool chipping.
Continuous chip	Good surface finish, steady cutting forces, undesirable in automated machinery.
Built-up edge chip	Poor surface finish, thin stable edge can protect tool surfaces.
Discontinuous chip	Desirable for ease of chip disposal; fluctuating cutting forces, can affect surface finish and cause vibration and chatter.
Temperature rise	Influences tool life, particularly crater wear, and dimensional accuracy of workpiece; may cause thermal damage to workpiece surface.
Tool wear	Influences surface finish, dimensional accuracy, temperature rise, forces and power.
Machinability	Related to tool life, surface finish, forces and power.

Manufacturing Technology

Cutting Fluids

- ⌚ A fluid which is used in machining as well as abrasive machining processes to reduce friction and tool wear

Function of cutting fluids

- ⌚ Lubrication
- ⌚ Cooling
- ⌚ Chip removal

Types

- ⌚ Straight Oil (Petroleum based oils)
 - ⌚ Soluble Oil (water based oils)
-