

CR

L

CR

HTF

IRM

WT

FV

FV

WS

L1

L11

HP

CV

FV

SWM

L2

L12

ALM

CV

FV

IRDM

L3

WLM

HP

S/A13

FV

1pG

L4

SM

FV

1pG

L5

SGM

WSM

L6

MM

IDM

L7

CGM

WM

L8

IRGM

IF

L9

L10

Work shop Layout

Sr.No.	Symbols	Fullform
1	CR	ClassRoom
2	HTF	Heat Treatment Furnace
3	FV	Fitting Vice
4	WS	Wooden Saw
5	SWM	Spot Welding Machine
6	L1 to L12	Lathe Machines
7	WLM	Wooden lathe machine
8	SM	Shaper Machine
9	SGM	Surface Grinder Machine
10	HP	Hydraulic Press
11	ALM	Automatic Lathe Machine
12	MM	Milling Machine
13	CGM	Cylindrical Grinding Machine
14	RGM	Radial Grinding Machine
15	PG	Pedestal Grinder
16	RDM	Radial Drilling Machine
17	WSM	Wooden Saw Machine
18	DM	Drill Machine
19	WM	Welding Machine
20	IF	Induction Furnace
21	CV	Carpentry Vice
22	RM	Raw Material
23	WT	Welding Table